

The Highland Council: Scheduled Watercourse Maintenance Works - Pending

Works Number	Watercourse Name	Location	Date for Re-Inspection*	Description of Works
1	Eil Burn	Station Road beside "Eilburn"	20/11/2015	Remove debris and clear culvert inlet.
204	Craggan Mill Burn	A95 at Craggan Mill, Grantown-on-Spey	09/06/2015	Vegetation and silt build up at culvert inlet/outlet and through culvert to be removed as it is causing a partial blockage and potential flood risk. BEAR informed of works required.
216	Rhives Burn	Ben Braggie car park	30/03/2015	Remove debris and repair the collapsed culvert in the Ben Braggie car park. Landowner contacted and asked to carry out works.
222	Ussie Burn	Behind Cottage Bar, Maryburgh	27/11/2015	Branches and debris causing a partial blockage in the burn. Land ownership uncertain
224	Blair of Tarradale Burn	A832 200m west of B9169 junction	15/04/2015	Debris and vegetation to be cleared from culvert inlet.
227	Gillibrath Drain	Railway by A830/B8006 junction, Corpach	16/11/2014	Culvert and watercourse leading to culvert to be cleared of vegetation and silt/debris build up. Network Rail informed of works required.
246	Culloden Burn West	Culloden Wood	21/01/2015	Trackside ditch leading to Culloden Burn West, immediately upstream of forestry track culvert, has become untidy. Gorse and any logs/debris within the ditch to be cleared out. Landowner contacted and asked to carry out works.
267	Macrae Grove Burn	To the rear of 12 Macrae Grove	15/04/2015	Ditch at culvert inlet is overgrown causing partial blockage of the screen. Area immediately upstream of screen to be cut back and dead vegetation removed. Landowner contacted and asked to carry out works.
279	Tain Burn 2	11 Rowan Drive, Tain	22/11/2014	Overgrown bush on banks of burn is causing debris to be caught and creates a blockage in the watercourse at a location where overtopping risk is greater. Bush to be cut back and any debris removed from site.
280	Ryefield Burn 2	B9163 at Alcaig	26/05/2015	Build up of sediment has partially blocked the rhs culvert. Inlet and outlet area to be cleared of sediment up to max 5m from culvert headwalls. Partially complete.
284	Mill Burn	Opposite 35 Harris Road	24/03/2015	Scottish Water sewer outfall headwall is partially collapsed into the watercourse. Headwall to be repaired. Scottish Water informed of works required.
296	Kinellan Burn	Adjacent to A834, upstream of St Anne's Episcopal Church	13/12/2014	New screen arrangement to be designed and installed at culvert inlet to replace existing damaged screen.
330	Ault na Skiah	Upper Slackbuie	15/04/2015	Woody debris to be removed from screen which is 80% blinded. Gravel deposits to be cleared from upstream side of screen also.
332	Pitmain Burn	A86, Kingussie	21/04/2015	Culvert inlet and outlet partially blocked with sediment and cobbles. BEAR informed of works required
334	West Terrace Burn	A86, Kingussie	21/04/2015	Channel heavily sedimented and culvert and road gullies choked. BEAR informed of works required.
336	Guisach Burn	A830, Corpach	20/04/2015	Sump and trash screen heavily sedimented. BEAR informed of works required.
338	Balantoul Burn	Fort Augustus	25/01/2015	Clearance of vegetation and debris from bypass/overflow channel
343	Eil Burn	Conon Bridge	15/04/2015	Clear watercourse of sediment and debris for 10m upstream of screen
349	Ben View Burn	Marybank	18/02/2015	Culverted field access in poor state of repair and beginning to collapse. Repair to damaged sections required. Will replace with new culvert Works re-issued 18/03/15
355	Fairburn Well	Marybank	16/03/2015	Poor conveyance through culvert due to sediment build up. Clear sediment immediately upstream of culvert and jet.
357	River Peffery	Burns Crescent	16/04/2015	Trees blown over and lying in/across the peffery. Remove from watercourse.
358	Lochardil Burn	Lochardil Road	15/04/2015	Tree across burn. Remove from watercourse.
360	Ashburn	Fort William	20/04/2015	Sediment build up in front of culverts. Remove material from site.
362	Slackbuie Channel	Upstream, Culduthel Road	28/04/2015	Trees growing in the Burn. Remove trees retaining the stumps to prevent erosion
367	SWFRC	Essich Road	15/04/2015	Trash screen partially blinded. Clear and remove material from site.
368	Davidston Burn	Shore Mill, Cromarty	03/05/2015	Watercourse has cut new route through field and is discharging to culvert under road. Culvert is in need of some repair.
369	Ashburn	Fort William	21/05/2015	Clear debris from the watercourse and culverts.
370	Kirkhill Burn	Wardlaw Road, Kirkhill	25/05/2015	Debris requiring removal from parts of the watercourse that act as roadside verge
373	Tower Burn	Cranmore Drive	10/06/2015	Suspected debris from tree clearance work left in burn causing blockage risk. Remove from Burn. Passed to SSE.
374	Jubilee Park Drain	Jubilee Park, Dingwall	16/06/2015	Build up of debris in front of the culvert that carries water from the Jubilee park drain through the flood bank to the Peffery. Material to be removed.
375	Parks Farm Burn	Culvert under southern distributor road	22/06/2015	Sediment bar has built up at the outfall of the culvert under the southern distributor road. Remove this to allow free flow through the culvert.
376	Parks Farm Burn	Trash screen downstream of southern distributor road	22/06/2015	Build up of debris and litter at and around the trash screen. Remove from site.
377	Mill Burn	Southern distributor road culvert	21/06/2015	Woody debris caught on central pillar of the bridge. Remove from site.
378	Mill Burn	Footbridge between Merlin Crescent and Mackenzie Park Gardens	21/06/2015	Tree root caught below deck of bridge. Remove from site.
379	Mill Burn	Sluice gate at Millburn Court	21/06/2015	Branches and debris building up in front of the old sluice gate workings. Remove from site.
380	Mill Burn	Harbour Road Culvert	21/06/2015	Build up of sediment and woody debris on right bank at upstream side of bridge. Remove from site.
381	Dell Burn	Beechwood Business Park	16/06/2015	Trees and woody debris causing flow restrictions on a 50m section of burn. Remove debris and overhanging tree branches
382	Dell Burn	Tesco Inshes	16/06/2015	Material and debris (leafy matter) building up in channel and particularly the banks in front of trash screen. Clear all loose material from 10m section upstream of screen.
383	Brown Terrace Burn	Kinlochleven	21/05/2015	Rocky debris and sediment building up at the culvert outfall. Clear a 10m section to hard (constructed) bed level from the culvert outlet.
385	Auldearn Burn	Newmill	18/06/2015	Sediment buildup in front of bridge causing a restriction to flow. Remove from watercourse.
388	Druid Temple Burn	Drakies Playing Field, Grebe Avenue.	24/06/2015	Fallen tree lying within the watercourse causing a partial blockage. Remove tree and trapped debris from the watercourse.
389	Lochardil Burn	Lochardil Road	30/06/2015	Tree fallen across watercourse and catching debris. Remove tree and debris from the watercourse.
390	Lochardil Burn	Lodge Park	30/06/2015	Fallen branch across the watercourse and catching debris. Remove tree and debris from the watercourse

* The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out