The Highland Council: Scheduled Watercourse Maintenance Works - Pending

-			-	
Works	Watercourse Name	Location	Date for Re-	Description of Works
Number			Inspection*	
500	South Kessock		40/00/0005	
580	Seawall	3 Areas in the seawall	19/02/2025	Repair missing stones sets in the seawall
000	Dingwall Flood		05/07/0004	
608	Defences	Canal footpath At victoria park	05/07/2024	Infill and seal holes in the embankment where rabbits have been burrowing.
044	Dingwall Flood		05/07/0004	
611	Defences	Canal footpath At victoria park	05/07/2024	Cut back and strim all vegetation growing in and along the flood embankment
626	Mill Burn	Culvert under Sir Walter Scott Drive	10/09/2024	Remove all silt and stone deposation from the inlet and ditch 10m upstream from the inlet
628	Druid Temple Burn	Druid Temple Crescent, Inverness	10/09/2024	Remove all silt and stone deposation from the inlet and ditch 10m upstream from the inlet
		Next to the playing ground at Grebe Avenue		
633	Druid Temple Burn	Hall	10/09/2024	Remove all vegetation lying in and across the burn which is restricting forward flow of water
		Adjacent to the Distributor Road (B8082)		remove silt accumulations from the culvert inlet which has reduced the culvert width by approx 50%, please remove any self seeded trees that
635	Ault na Skiah	behind properties on Castle Heather Avenue	10/09/2024	are growing in the burn or on the burn sides.
636	SWFRC	SWRFC numerous locations	10/09/2024	Remove all vegetation gorse/whin are growing on the crown and sides of the flood relief channel. Currently growing is numerous areas
641	Eil Burn	Behind Burnside Lane	05/09/2024	Remove vegetation along ditch. Priority increased following updated observation of increased weed growth.
	Dingwall Flood			
651	Defences	Sections 3, 4 and 5	23/07/2024	Complete clearance of all vegetation growing in sections 3, 4 and 5 of the flood defences
				Silt accumulations and a build up of debris/rubbish at the culvert, some of which is lying at the twin culvert inlets, please remove as much silt as
658	Slackbuie Channel	Junction of Culduthel Road and Green Drive	10/09/2024	possible and ensure inlets are clear.
				The outlet of structure 60 is suffering silt and vegetation deposition approx 90% surchaged, the inlet of structure 70 has similar issues although
		Opposite the Veterinary Centre on the B9006		not surcharging, deposition is deflecting waterflows towards the sidewall, ditch burn 10 metres downstream from the outlet and 10m upstream
663	Beechwood Burn	Culloden Road	10/09/2024	from the inlet to return burn to original invert levels.
				The culvert outlet is 50% surcharged due to windblown trees and woody debris lying across the watercourse for the majority of the open section
664	Ault na Skiah	Culvert outlet opposite Evan Barron Rd	10/09/2024	down to the boundary fence of the property. Clear all woody debris from the open section.
		Near Passing Place Lay-by next to Brahan		Heavy Vegetation surrounding Inlet & all along Bank Upstream to Structure 60 & Downstream to S72. Vegetation to be cut back 10m Upstream
690	Ben View Burn	View, Upper Arcan Road Marybank.	05/08/2024	from Inlet of S70 & all along Downstream between S70 & S72.
		Knockbain Silt Traps, Blackwells Court.		Silt build up across all 3 Screens, particularly in far left & right Screens. Very Large Stone washed down into Screen on LHS facing D/S. All Silt in
694	Knockbain Burn	Dingwall	05/08/2024	3 Screens to be ditched out & removed.
702	Tain Burn 2	Within St Vincent Estate	26/06/2024	Section 18 Letter issued to the Homeowners. Heavy Vegetation & Woody Debris within a section of the Watercourse within property boundaries.
703	Miller Road Burn	Miller Road, Cromarty	13/11/2024	Silt build up along Watercourse D/S from Outlet and within Culvert itself. Silt to be removed/ ditched to ensure unrestricted flow.
708	Hill Terrace Burn	Hill Terrace, Kinlochleven	30/08/2024	Wire Fence along Bank collapsed should be repaired to prevent blockages & prevent public falling in.
710	Hill Terrace Burn	Hill Terrace, Kinlochleven	30/08/2024	Silt/ Stone build up near Inlet. Should be removed to ensure unrestricted flow.
714	Slackbuie Spring	Upper Slackbuie along SWFRC, Inverness.	04/09/2024	Vegetation on spill to be cut down to geo fabric underneath.
719	Mill Burn	Sluice Gate near Millburn Court, Inverness	10/09/2024	RHS of Sluice blocked with Debris, forcing all Waterflow into LHS should be cleared.
7 13	IVIIII DUITI	Sidice Gate flear Millibuth Court, invertiess	10/03/2024	Screen blocked & surcharged, Water overtopping Screen into WC but not on to Banks. Most of the blockage is Silt build up, which has built up.
721	Scretan Burn	Caulfield Road North, Inverness	11/09/2024	Remove silt.
724	Knockbain Burn	Knockbain Burn, near Gorstan, Dingwall	06/07/2024	Build up of Silt on LHS near Screen - Should be cleared
724	KIIOCKDAIII DUIII	Kriockbailt Butti, flear Gorstaff, Birlgwaii	00/01/2024	Debris & Large Branches blocking RHS of Culvert Inlets, there is also a build up of Silt/ Stones within the Outlet of the middle Culvert. Debris
726	Kylintra Burn	Woodburn Crescent, Grantown-on-Spey	11/07/2024	should be removed & Silt ditched out of Culvert.
720	Nyiirilla Durii	Debris Screen near SSE Garage, A82 Fort	11/01/2024	Screen Blocked & Surcharged 50% from Large Debris & Leaves. Rest of Screen to be cleared with large Debris removed. Side-cast Debris to
728	Balantoul Burn	Augustus.	22/08/2024	removed also.
730	Ardival Burn	Rear entrance to Wyvis Hotel, Strathpeffer	06/07/2024	Old Stone Culvert has collasped, causing Inlet to Pool/ Surcharge & overtop over Road. Culvert to be replaced with new Pipe & Headwall.
7.50	Aluivai Dulli	· · · · · · · · · · · · · · · · · · ·	00/01/2024	
722	Olvin Comata D.	Olrig Cemetery, road leading to St Trothan's	26/00/2024	Dual Stone Culvert/ Cundy has collapsed in middle of Culverted section parallel to Road. Multiple piles of side-cast Debris surrounding Screened
732	Olrig Cemetery Burn	Church, Castletown	26/08/2024	Inlet U/S. Repair/ replace collapsed section, collect side-cast Debris near Screen.
	South West Inverness		0.4/0.0/2.2.5	
733	Flood Relief Channel	Inverness	04/09/2024	Lower Screen 50% blocked with Vegetation. Screen should be cleared entirely to ensure un-restricted flow
	l	Underneath Bridge on B862, near Holm Lodge.		
738	Holm Burn	Inverness	10/09/2024	Tree Limb stuck underneath Bridge on B862. Limb will need to be removed.
				Stone/ Concrete Culvert Pipe has collasped causing Water to back up and overflow down towards the Property. Homeowners property, it is the
739	Swordale Burn	Bonar Bridge	18/10/2024	responsibility of the Homeowner to undergo the Works required.
				Partial blockage and likely collapse of stone culvert within 2m of Manhole. Section is estimated to be below footpath. Callapse to be repaired and
741	Park Burn	Park Road, Sstrathpeffer	05/09/2024	blockage removed.
				During a SW incident in Feb the Culvert backed up & overtopped, increasing the Waterlevels of the nearby Essich Burn which lead to multiple
				properties within the area to be flooded externally. Waterlevels were too high during Insp to conclude the cause of blockage (collapse or debris).
				07/05/2024 - Waterlevels had decreased and Inspector was able to look within Culvert. Culvert is blocked with washed down Debris, Leaves &
				Silt. Inspector unable to remove bulk of Debris during Insp. As Culvert is located under private road, a S18 Letter has been issued to all
742	Essich Burn	Ness Castle Drive	02/07/2024	properties that access via Ness Castle Drive to have Culvert cleared.
743	Guisach Burn	Treasures of the Earth Museum	25/07/2024	Screen blinded by sediment. BEAR contacted to clear the screen.
744	Mill Burn	Section between Mason Road & Teal Avenue	10/09/2024	Fallen Trees lying within the Watercourse accumulating Derbis. Trees & Debris to be removed to ensure un-restricted flow.
		Trash screen upstream of railway bridge behind		
746	Smithton Burn	Murray Terrace, Smithton	11/09/2024	RHS of Screen blocked with washed down Debris, Silt, Stones etc. Should be removed to ensure un-restricted flow.
	. 			

^{*} The stated date for re-inspection denotes when the re-inspection is due and not when the works are due to be carried out