

The Highland Council: Scheduled Watercourse Maintenance Works - Complete June/July 2024

Works Number	Watercourse Name	Location	Date Works Carried Out	Description of Works
702	Tain Burn 2	Within St Vincent Estate	25/06/2024	Section 18 Letter issued to the Homeowners. Heavy Vegetation & Woody Debris within a section of the Watercourse within property boundaries.
717	Lochardil Burn	Along Sir Walter Scott Drive (A8082), Inverness.	18/06/2024	Screen has been tilted & raised by small log/ stump. Stone silt washed up LHS near Screen & centre slightly U/S. Silt to be ditched & removed & Screen to be returned to original position.
734	Scretan Burn	Caulfield Road North, Inverness	19/06/2024	Inlet blocked with Wooden Debris. Debris should be removed to ensure un-restricted flow.
736	Tower Burn	Rowan Grove, Inverness	19/06/2024	Washed down Debris accumulating on Screen, buried underneath mound of Silt/ Stones etc. Debris should be cleared to allow the Silt/ Stones to wash downstream.
737	Culloden Burn West	Culloden Woods, Footpath that runs behind Loch Lann Ct & Redburn Ave	19/06/2024	Screen blocked with washed down Debris, Silt, Stones etc. Should be cleared to ensure un-restricted flow.
742	Essich Burn	Ness Castle Drive	02/07/2024	During a SW incident in Feb the Culvert backed up & overtopped, increasing the Waterlevels of the nearby Essich Burn which lead to multiple properties within the area to be flooded externally. Waterlevels were too high during Insp to conclude the cause of blockage (collapse or debris). 07/05/2024 - Waterlevels had decreased and Inspector was able to look within Culvert. Culvert is blocked with washed down Debris, Leaves & Silt. Inspector unable to remove bulk of Debris during Insp. As Culvert is located under private road, a S18 Letter has been issued to all properties that access via Ness Castle Drive to have Culvert cleared.